


Fig. 2






FIG. 3

FIG. 4A





FIG. 4B




FIG. 5A




FIG. 5B




FIG. 5C





FIG. 6A

(a) Top view.



(b) Side view.

FIG. 6B




FIG. 7




FIG. 8

FIG. 9A




FIG. 9B




FIG. 10




FIG. 11





FIG. 12

FIG. 13A




FIG. 13B




FIG. 13C




FIG. 13D




FIG. 14A

FIG. 14B




FIG. 14C

FIG. 15A




FIG. 15B




FIG. 16





FIG. 17

FIG. 18C




FIG. 18A




FIG. 18D





FIG. 18B

FIG. 19C

(Side view across the
torsion spring 60)




FIG. 19A




FIG. 19D





FIG. 19B




FIG. 20




FIG. 21





Fig. 22








Fig. 23









FIG. 26




FIG. 27




FIG. 28




FIG. 29

FIG. 30A




FIG. 30B




FIG. 31

FIG. 32A





FIG. 32B




FIG. 33




FIG. 34




FIG. 35

FIG. 36A





FIG. 36B

FIG. 37A





FIG. 37B

FIG. 37C






FIG. 37D

FIG. 38A



Top view




FIG. 38B